IMV-WMJB
Junction Box

Installation Guide

C6695M

Installation

① A 3/4" conduit is required for routing the cables with waterproof connection. The cable gland and conduit are user-supplied.

If using the bottom hole, seal the center hole.

If you use the bottom hole, install the seal plug to the unused hole in the center.

Mounting Dimensions

51.00   51.00
ø5.20
UNIT:mm
51.00
51.00

Package Contents

UNIT:mm

② Attach the included alignment sticker to a preferred position. Drill holes on the wall and install the junction box. If space behind the wall allows, you may also pass cables through the wall.

③ Install the cable gland and pass cables through it.

OR

3/4"

④ Secure SRXV-WMP Wall Arm to box using the hex socket screws.

⑤ Refer to the accessories' and camera's QIG for more information.